



American Legend Aircraft Company
1810 Piper Lane
Sulphur Springs, Texas 75482
903-885-7000
<http://legend.aero>

SERVICE BULLETIN

American Legend Aircraft Company considers compliance mandatory

Notification Number: **SB-06-11-12-1**

Number of pages: **1 of 2**

Superseded notices: **061001 Rev. A**

Date Release: **Revised July 13, 2007**

Date in Effect: **Effective October 12, 2006**

Affected Make: **American Legend Aircraft**

Affected Models: **AL3, AL11**

Affected Serial Numbers: **serial numbers AL-1005 to AL-1055**

Subject **Fuel hose, wing to fuselage**

Service to be performed by **The holder of a mechanic certificate with airframe or powerplant rating(s), or both, or a LSA Repairman.**

Tools required **Phillip and flat screw driver, wire cutters, pliers**

American Legend Aircraft Company suggest the replacement of the fuel hoses that connect the fuel tank to fuselage fittings with fuel hose part number 350-PP0100/4”.

A kit containing this material can be ordered from American Legend Aircraft Company. Kit part number is, 200 PP0103/Kit, Black Fuel Line, Tank to Hard Line Connector, 4 pcs.

The existing hose clamps can be re used and should be tightened and torqued to 3 in pounds.

It will be the responsibility of the owner/operator to comply with all released SAFETY ALERTS, SERVICE BULLETINS, NOTIFICATION and Airworthiness Directives as applicable. All inspection procedures and maintenance schedules must be accomplished per the manufacturer's recommendations.

For more information please contact us at the above address or by E-mail at "Service@legend.aero"